

****EPA Notice****

On 4/20/22 samples from wells 2, 3 & 5 were taken and tested by Suburban Labs Inc for iron content. We were informed today (6/28/22) that wells 2 & 5 were found to have higher than normal iron levels. In an attempt to correct this in the pumps in these wells were raised 20 feet each. We will also be scheduling a blow off of these water systems to remove any existing iron from the lines. We will send out notification prior to the blow off being done. NO BOIL ORDER IS NEEDED & there is not health hazard for this issue.